



CORNER HISTORY: Corner originally set as a post in 1821 by Wm. B. Laughlin with witness: 20" buckeye S 15 E 25 links; 20" dogwood N 46 W 3 links per Marion County Atlas pg. 12. A survey dated 10-1893 by Paul Julian called stone set per Washington Township Legal Survey Book pg. 11. Survey dated 4-5-1894 by Paul Julian called stone already set per Washington Book pg. 40. Reference dated 11-25-1949 by Gioscio called stone found. Reference dated 1-16-1952 by Monroe called found stone 15" down. Reference dated 8-31-1977 by Miller called railroad spike. Reference dated 2-10-1987 by Gries called two railroad spikes were found at 0.10' apart. Didn't dig because of a 48" cmp crossed over the corner. Reference dated 2-2-93 by Wilcoxen called a PK nail.

1998 a Hamilton County road construction project destroyed the original monumentation for the section corner. The construction contractor was required by the Hamilton County Surveyor's Office to replace the marker with a Harrison Monument. In August 1998 the Marion County Surveyor's Office discovered the Harrison had been set incorrectly. This information was relayed to the Hamilton County Surveyor's Office. With a combined effort by Hamilton and Marion, the original corner location was found using Marion County GPS coordinates established before construction. Hamilton County than reset the Harrison in the original location. July 1998 Marion County again had reason to question the location. Marion County checked the location with GPS coordinates and found the monument was in the correct location. Reference dated 8-9-1998 by Wilcoxen called for a Harrison.

REF.	DISTANCE	DESCRIPTION
1.	63.95'	PK nail w/brass washer E PwP#11-172 A 8"up
2.	189.52	PK nail w/brass washer S PwP#12-172A 24"up
3.	155.23'	Top nut of fire hydrant
4.	66.82	PK nail w/brass washer W PwP#10-172 B
5.	93.25	SE corner of brick sign "Farmers INS"
6.	94.45	Center of top of R/W marker